




# RIVER MILE 10.9 REMOVAL ACTION WATER QUALITY MONITORING PROGRAM WEEKLY REPORT

## Summary of water quality monitoring for the week ending August 3, 2013


Dredging operations, which began on August 3, 2013, are being continuously monitored to ensure that water quality is maintained at acceptable levels within the River. To monitor water quality, a number of sampling locations have been established shown on the map below.


*Operations were conducted within acceptable water quality limits.*



## Water Quality Monitoring Data

Buoy #	Turbidity (NTU)	
	Weekly Average	Std Deviation
1	8.2	2.4
2	15.3	9.3
3	6.1	1.6
4	6.5	0.8





Water Quality Monitoring Locations